

August 2008

Latest Software and Firmware for Construction

Last Updated: 1st August, 2008

For notices of updates to Software for firmware via [RSS](#) 

Note: Release dates are only included for software and firmware released since May 2004

Product	Software	Firmware	OS	Release date	Available from
Site Positioning Systems					
5600 (PVX)		696-03.08			Service Center
5700		2.32		May 2007	Trimble.com
5800		2.32		May 2007	Trimble.com
ATS (PVX4S E 00)		696-03.08	698-02.00		Service Center
ATS (PVX4S E 01)		796-03.08	798-02.00	October 2006	Service Center
DSM12/212		1.71			Trimble.com
DSM132		3.00		October 2005	Trimble.com
DSM232		3.59		August 2007	Trimble.com
Geodimeter® CU new board		669-02.04			Service Center
Geodimeter CU old board		632-11.04			Service Center
MS750™		1.58		September 2006	Trimble.com
SPS700		R6.1.92		December 2007	Trimble.com
SPSx10		R6.1.92		December 2007	Trimble.com
SPSx30		R6.1.92		December 2007	Trimble.com
SPS770		2.32		May 2007	Trimble.com
SPS780		2.32		May 2007	Trimble.com
SPS781		3.64		June 2008	Trimble.com
SPSx5x		3.65		July 2008	Trimble.com
SPS88x		3.64		June 2008	Trimble.com
ACU (SCS900, English)	2.33		4.0.12	March 2008	Trimble.com
TCU (SCS900, English)	2.40		4.2.5.12/ 5.0.0.19	June 2008	Trimble.com
TSC2 (SCS900, English)	2.40		5.0.3	June 2008	Trimble.com

Trimble Construction Division, 5475 Kellenburger Road, Dayton, OH 45424, USA

© XXXX, Trimble Navigation Limited. All rights reserved. Trimble, the Globe & Triangle logo, XXX, XXX, and XXX are trademarks of Trimble Navigation Limited, registered in the United States Patent and Trademark Office and in other countries. XXX, XXX, and XXX is a/are trademark/trademarks of Trimble Navigation Limited. All other trademarks are the property of their respective owners.



Product	Software	Firmware	OS	Release date	Available from
TSCe (SCS900, English)	2.33		4.0.12	March 2008	Trimble.com
Tablet (SCS900, English)	2.40		Windows XP/Vista	June 2008	Trimble.com
ACU (SCS900, Other Languages)	2.32		4.0.12	March 2008	Trimble.com
TCU (SCS900, Other Languages)	2.32		4.2.5.12/ 5.0.0.19	March 2008	Trimble.com
TSC2 (SCS900, Other Languages)	2.32		5.0.3	March 2008	Trimble.com
TSCe (SCS900, Other Languages)	2.32		4.0.12	March 2008	Trimble.com
Layout Systems					
LM80 V4.x	4.21		Mobile 6	May 2008	Trimble.com
LM80 V4.x	4.21		Mobile 5	May 2008	Trimble.com
LM80 V4.x	4.21		Pocket PC	May 2008	Trimble.com
LM80 V3.x	3.23		Mobile 5	April 2007	Trimble.com
LM80 V3.x	3.23		Pocket PC	April 2007	Trimble.com
LM80 Desktop	2.21			May 2008	Trimble.com
SPSx10		R6.1.92		December 2007	Trimble.com
SPSx30		R6.1.92		December 2007	Trimble.com
SPS700		R6.0.38		July 2007	Trimble.com
Radio Infrastructure Systems					
TNR900		1.24		January 2008	Trimble.com
SNB900		1.24		July 2007	Trimble.com
Trimble PDL 450		2.42		February 2007	Trimble.com
TRIMMARK™ 3		1.30		February 2008	Trimble.com
TRIMTALK™ 450S			2.15		N/A
GeoRadio			626-06.07		Service Center
GeoRadio 2.4 GHz			626-08.02	December 2005	Service Center
GCS Series Components					
AS21		1.54	4.37		Dealer
AS400		3.04		Jan 2007	Dealer
CB410		1.10		May 2007	Dealer
CB420		2.51		October 2007	Dealer
CB430		10.80		April 2008	Dealer
CM310		1.04		April 2008	Service Center
EM400		1.86		October 2006	Dealer
LR400		1.83		November 2006	Dealer
LR410		1.88		November 2006	Dealer
MS980		1.39	1.10	April 2008	Dealer

Product	Software	Firmware	OS	Release date	Available from
MS990		3.61	3.21	April 2008	Dealer
MT900		1.09		July 2007	Dealer
RS400		1.89		October 2006	Dealer
SiteNet™ 450		1.28		October 2005	Trimble.com
SR300		2.31		July 2007	Dealer
SNRx10		5.02		July 2008	
SNR900		3.18		February 2007	Trimble.com
SNR2400		1.06		July 2006	Dealer
ST400		1.03		May 2007	Dealer
SV170 (GCS900)		6.11	2.12.021	October 2006	Dealer
VM410		1.74		December 2006	Dealer
VM415		1.00		April 2008	
VM420		1.87		July 2007	Dealer
Office Software Products					
Configuration Toolbox™	6.70			October 2007	Trimble.com
DC File Editor	2.03				
Grid Factory	1.41				Trimble.com
MS Controller™	1.1.0.0				
Paydirt® Roadwork	2.0.3				Trimble.com
Paydirt Sitework	5.22			February 2004	Trimble.com
Paydirt Trenchwork	2.00				
Planning	2.74				Trimble.com
SiteVision Office	7.10			April 2008	Dealer
SCS Data Manager	2.40			June 2008	Trimble.com
SCS Reporting Utility (English)	2.40			June 2008	Trimble.com
SCS Reporting Utility (Other Languages)	2.32			March 2008	Trimble.com
Terramodel®	10.52			March 2007	Trimble.com
Trimble Business Center- HCE	1.10			December 2007	Trimble.com
Trimble Exchange	2.3				

Product	Software	Firmware	OS	Release date	Available from
Trimble Office Synchronizer	1.44			March 2008	Trimble.com
Marine Construction Software					
HYDRO ^{pro} ™	2.32			February 2008	
DSM Utility	1.03			April 2007	Trimble.com
SiteVision® GPS Machine Control					
AS21		1.54	4.37		Dealer
MS850™		1.58		September 2006	Trimble.com
MS860™		1.58		September 2006	Trimble.com
SiteNet™ 450		1.28		January 2005	Trimble.com
SiteNet™ 900		2.78		December 2006	Trimble.com
SV170 (SiteVision)		5.52	2.12.021	June 2005	Dealer
TRB		3.66			Dealer
BladePro® Machine Control					
0365-2040 Operator Interface Box		4.20			
0365-1140 Remote Box		6.70			
BladePro® 3D Machine Control					
0365-1140 Remote Box		6.70			
0366-2010 Graphical Operator Box	3.4C01	Loader 1.0C07	NT 4.01	Aug 04	
RTX		4.3.1			
System Softcard		5.2			
ScreedPro® PA Control					
CSM-30 Slope Module		4.3			
LM-25 Laser Interface Module		4.5			
R-25 Universal Remote		4.7			
ST2-25CE Sonic Tracer		4.5			